## Express

## **Belgotex**<sup>®</sup>

Designers Choice	Image: Second state sta
Construction	Luxury Vinyl Tile
Plank Size	177.8 x 1219.2mm
Tiles per Carton	20pcs / 4.335m <sup>2</sup>
Total Weight	3550g/m <sup>2</sup>
Wearlayer Thickness	0.3mm
Total Thickness	2.0mm
Surface Protection	High Performance PU
Finish	Embossed
Bevel	4-sided micro-bevel
Slip Resistance	R10 (DIN 51130)
Electrical Propensity	0.1kV (EN 1815)
Fire Rating	CRF ≥ 11.0kW/m² (ISO 9239-1)
Acoustic Insulation	3dB (EN ISO 10140-3)
Dimensional Stability	/ ≤ 0.25 % (EN ISO 23999)
Thermal Conductivity	0.074 (W/m*K) (EN 12664)
Thermal Resistance	0.027 (m2*K/W) (ISO 12664)
Indoor Air Quality	FloorScore® A+ Emissions Eurofins Gold Certified
Underfloor Heating	Suitable, max 27°C
Residual Indentation	< 0.1 mm (ISO 24343-1)
Colour Fastness	Grade 6 (ISO 105-B02:2014)
Classifications	Class 23 Domestic Heavy / Class 31 Commercial Light
Warranties	LVT Warranty 20 Year Residential Warranty 10 Year Commercial Warranty
Environmental	Greentag Certified Environmental Product Declaration GREENGUARD Gold Certification Declare ISO 9001, ISO 45001, ISO 14001
Installation	Please contact Gilt Edge Industries for all adhesive and installation instructions. NB: If recommended adhesive is not used, claims will not be accepted. Must be laid in accordance with AS/NZ Installation Standards.

■ For samples, range and warranty details please contact us on 0800 377 753 or belgotex.co.nz

- Specifications are based on averages from manufacturing processes and may vary within normal industry tolerances.
- This product is intended for use solely as an indoor floor covering and is not recommended or sold for any other purpose.
- Use entryway systems outside each entrance to prevent dirt, sand, grit and other substances from being tracked onto floor.
- Rubber Migration: Rubber migration (also known as Plasticiser Migration) is a condition that can cause vinyl to discolour. It is caused by rubber or latex products, eg rubber or latex-soled slippers, shoes and rubber backed mats, coming to contact with the vinyl over a constant period of time. It is neither a manufacturing nor an installation fault and therefore is not covered by our warranties.