L.V.T. Moduleo Moods

Specifications:

□ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □ □	Castor wheel resistant	Thermal	Antistatic	Stain resistant	Long	Great for families	Bacteria and mould resistant	
stability	resistant	resistance	covering	resistant	lasting	Tamilies	mouid resistant	
Level of use -			23 – 33	- 42				
Total thickness -				2.5 mm				
Wear layer -				0.55 mm				
Wear layer PUR treatment -				Protectonite®				
Total weight -				4059 g/m ²				
Size & Packaging -			-	Size (mm) Pieces/box M ² /box				
Triangle	(NZ Stocked)		•	452.64 x 392.00 17			1.51	
Chevron	, (NZ Stocked		522.67	x 92.40	2.40 42 2.03			
Big Hexagon (NZ Stocked except Desert Crayola colours				452.64 x 392.00 17 2.26				
Diamond	(Indent Product)		•	113.16 x 196.00			1.46	
Hexagon	(Indent Product)		226.32	226.32 x 196.00		44	1.46	
Parallelogram	(Indent Product)		452.64	452.64 x 196.00 17		17	1.51	
Small Plank	(Indent Product)		261.33	261.33 x 65.33 1		116	1.98	
Trapezoid	(Indent Product)		452.64	452.64 x 196.00 34		34	2.26	
Big Diamond	(Indent Pro	duct)	226.32	x 392.00		51	2.26	
Inflammability -			Bfl-S1	Bfl-S1				
Critical Radiant Flux -			8.9kW/	8.9kW/m2				
Scratch resistance -			Class T	Class T				
Squareness & straightness -			≤ 0.25 r	≤ 0.25 mm				
Slip resistance -			DS	DS				
Slip restraint -			R10	R10				
Residual indentation -			Norm: s	Norm: ≤ 0.10 mm, Average result measured ≤ 0.03 mm				
Furniture leg resistance -				No cracks, no damage				
Electrical resistance -			≤ 10 ⁹ Ol	≤ 10 ⁹ Ohm				
Dimensional stability -			Norm: s	Norm: ≤ 0.25 %, Average result measured ≤ 0.05 %				
Heat insulation -				0.25 w/(m.K)				
Thermal resistance R -			0.0100	m ² K/W				
Electrostatic performance -			< 2 kV	< 2 kV				
Acoustic insulation -			3 dB	3 dB				
Castor chair resistance -				No damage to wearlayer, no delamination				
Stain resistance -				Very good				
Light fastness -				≥6				
Underfloor heating -				Suitable, max 27°C				
Warranty (year) -				10 Commercial				

• RUBBER MIGRATION: This is a condition that can cause vinyl to discolour. Migration occurs when latex or rubber products such as shoes, rubber backed mats or rubber soled slippers come into contact with vinyl over a period of time. This is not a manufacturing fault and therefore is not covered under our warranties.

• Warranties are extended to the original purchaser of the product only and are not transferable.

international flooring solutions

p 03 366 9839
e office@robertmalcolm.co.nz
59 Halwyn Drive, PO Box 914, Christchurch 8140, New Zealand
robertmalcolm.co.nz

robert malcolm

L.V.T. Moduleo Moods

Specifications:

Please contact us on 03 366 9839 to request sample or other product details.

international flooring solutions

p 03 366 9839
e office@robertmalcolm.co.nz
59 Halwyn Drive, PO Box 914, Christchurch 8140, New Zealand
robertmalcolm.co.nz

